Declassified in Part - Sanitized Copy Approved for Release 2014/02/26: CIA-RDP78-03330A004200070002-2


ATTN FROM

SUBJECT:

## Office Memorandum • UNITED STATES GOVERNMENT

Chief, EP	DATE: 29 <b>January 1960</b>	50X1
Leads Now Used	Determination of the Necessity of the two B plus	50X1
came under consi if the two 90 vo B plus lines in considerations. individual compo	to DC Converter for the operation of the determine of the laboratory was asked to determine of the original design stems primarily from mechanical That is, the reduced dissipation required of the onents when supplied into two separate lines would rever-all package. Actually, these two leads were in	50X1
the two B plus l was observed on am, cw, calibrat ance was noted. may be operated The AC ripple sh supply should be ripple and regul miniaturized DC	production testing of the units. However, omeration was rechecked by running tests on both the supplied from a common 90 volt source connected to lines tied in parallel. Operation of the receivers all bands in the various modes of operations, i.e., ion, etc. No spuriouses or degradation in perform—Therefore, the test indicates that the receivers from parallel B plus lines without decoupling. The product of the 90 volt is held to plus or minus 5%. Such conditions of lation should not be difficult to obtain in a to DC Converter. However, if it should become lax or lower these figures, additional tests should	50X1 50X1

50X1



50X1

## CONFIDENTIAL SECRET